

CLIENT:

Siam Gypsum Industry (Saraburi) Co., LTD. 1 Siam Cement Rd 2nd Floor, Building 6 Bangsue, Bangkok 10800 Thailand

Attn: Thossapon Satiraratana

Test Report No: 606559

Date:

May 25, 2006

The following sample was submitted by the Client as: Siding (Gypsum Board)

0.500" (1/2") Firestop and 0.625" (5/8") Firestop

DATE OF RECEIPT:

April 26, 2006

TESTING PERIOD:

May 24, 2005

AUTHORIZATION:

Order Confirmation Number 606559

TEST(S) REQUESTED:

The submitted sample was tested in accordance with the procedures

outlined in ASTM E136-98, "Standard Test Method for Behavior of

Materials in a Vertical Tube Furnace at 750°C".

TEST RESULTS:

The submitted sample complies with the requirements as specified in

ASTM E136-98.

PREPARED BY:

SIGNED FOR AND ON BEHALF OF

SGS U.S. TESTING COMPANY INC.

Fire Technology

Arthur D. Fiorino, Senior Technician

Fire Technology

Page 1 of 3

This report is issued by SGS U.S. Testing Company Inc. under its General Conditions for Testing Services, as printed on reverse side. SGS U.S. Testing's responsibility under this report is limited to proven negligence and will in no case be more than the amount of the testing fees. Except by special arrangement, samples are not retained by SGS U.S. Testing for more than 30 days. The results shown on this test report refer only to the sample(s) tested unless otherwise stated, under the conditions agreed upon. Anyone relying on this report should understand all of the details of the engagement. Neither the name, seals, marks nor insignia of SGS U.S. Testing may be used in any advertising or promotional materials without the prior written approval of SGS U.S. Testing. The test report cannot be reproduced, except in full, without prior written permission of SGS U.S. Testing Company Inc.



Report No.:606559

Date: May 25, 2006

Page: 2 of 3

CLIENT: Siam Gypsum Industry (Saraburi) Co., LTD.

RESULTS:

0.500" (1/2") Firestop

<u>Specimen</u>	Furnace <u>Temperature, °F</u>	Maximum Surface Thermocouple, <u>°F</u>	Maximum Interior Thermocouple, <u>°F</u>	Weight Loss, <u>Percent</u>
1	1382	875	1382	21.31
2	1382	840	1382	18.62
3	1382	885	1382	18.33
4	1382	850	1382	21.50

Observations: Discoloration, cracking.

	Original Weight	Final Weight
1	53.67	42.23
2	54.07	44.00
3	50.66	41.37
4	55.16	43.30

REQUIREMENTS:

Temperature of the surface and interior thermocouples does not, at any time during the test, rise more than 54°F above the furnace air temperature (1382°F) and there shall be no flaming from the specimen after the first 30 seconds. Also, the weight loss of the specimen during testing exceeds 50%, the recorded temperature of the surface and interior thermocouples do not at any time during the test rise above the furnace air temperature at the beginning of the test, and there is no flaming of the specimen.

CONCLUSION:

The submitted sample complies with the requirements as specified in ASTM E136-98.



Report No.:606559

Date: May 25, 2006

Page: 3 of 3

CLIENT: Siam Gypsum Industry (Saraburi) Co., LTD.

RESULTS:

0.625" (5/8") Firestop

<u>Specimen</u>	Furnace <u>Temperature, °F</u>	Maximum Surface Thermocouple, <u>°F</u>	Maximum Interior Thermocouple, <u>°F</u>	Weight Loss, Percent
1	1382	830	1382	16.10
2	1382	830	1382	8.33
3	1382	860	1382	17.23
4	1382	855	1382	11.82

Observations: Discoloration, cracking.

	Original Weight	Final Weight
1	59.80	50.17
2	65.50	60.04
3	66.09	54.70
4	67.73	59.72

REQUIREMENTS:

Temperature of the surface and interior thermocouples does not, at any time during the test, rise more than 54°F above the furnace air temperature (1382°F) and there shall be no flaming from the specimen after the first 30 seconds. Also, the weight loss of the specimen during testing exceeds 50%, the recorded temperature of the surface and interior thermocouples do not at any time during the test rise above the furnace air temperature at the beginning of the test, and there is no flaming of the specimen.

CONCLUSION:

The submitted sample complies with the requirements as specified in ASTM E136-98.

End of Report